


## Fitment Tip

### Z756 in-line fuel filter



Suits: Citroen C4, MINI Cooper, PEUGEOT 207, 307, 308, Partner

On first inspection the side water sensor plug appears to be blocked, however this seal will break once the water sensor is correctly screwed in.

TIP: There is no need to force or drill the hole – just keep turning the sensor until you hear a ‘click’.



#### AUSTRALIA

GUD Automotive Pty Ltd  
29 Taras Avenue, Altona North  
Victoria 3025 Australia.  
[www.rycofilters.com.au](http://www.rycofilters.com.au)

#### NEW ZEALAND

GUD Automotive - A division of GUD (NZ) Holdings Limited  
626A Rosebank Road Avondale  
Auckland, New Zealand  
[www.ryco.co.nz](http://www.ryco.co.nz)

#### SOCIAL NETWORKS

Facebook: <http://facebook.com/rycofilters>  
YouTube: <http://youtube.com/rycofilters1>  
Twitter: [http://twitter.com/Ryco\\_Filters](http://twitter.com/Ryco_Filters)