


RYCO FILTERS



FITTING INSTRUCTIONS FOR RYCO CABIN FILTER RCA291P. HYUNDAI ACCENT (MC)



- 1. The cabin air filter is located behind the glove box compartment. To gain access to the cabin air filter the unit requires removal.**
- 2. For better working space, slide the passenger seat all the way back. Open the glove box, remove the retaining strap from the box side then remove both top corner retaining lugs from the inside of the box so the lid can be dropped completely.**
- 3. Identify the cabin air filter housing and unclip the lid. Slide the old cabin filter out carefully to avoid any accumulated debris from being spread around and clean the area. Repeat the same process with the second filter. Note: set of 2 filters.**
- 4. Slide in the new filters making sure the face to the correct air flow direction. Refit all components in reverse order.**

GUD Automotive Pty Ltd
29 Taras Ave Altona North
Victoria 3025 Australia.
www.rycofilters.com.au

GUD Automotive -
A division of GUD (NZ) Holdings Limited
626A Rosebank Road Avondale
Auckland, New Zealand
www.ryco.co.nz